



KXA02NH

Neutral

Description	Cat ref.
Feed-through terminal-neutral , 2,5mm ² , 800V-24A, screw connection	KXA02NH
Feed-through terminal-neutral, 4mm ² , 800V/32A	KXA04NH
Feed-through terminal-neutral ,6mm ² , 1000V/41A, screw connection	KXA06NH
Feed-through terminal -neutral, 10mm ² , 400V/57A, screw connection	KXA10N
Feed-through terminal-neutral, 16mm ² , 400V/76A, screw connection	KXA16N
Feed-through terminal-neutral, 35mm ² , 400V/125A, screw connection	KXA35N
Feed-through terminal-neutral, 70mm ² , 1000V/192A, screw connection	KXB70NH



KXA02E

Earth

Description	Cat ref.
earth terminal, 2,5mm ²	KXA02E
Earth terminal, 4mm ² , screw connection	KXB04E
Earth terminal, 6mm ² , screw connection	KXB06E
Earth terminal 10mm ² , screw connection	KXA10E
Earth terminal, 16mm ² , screw connection	KXA16E
Earth terminal, 35mm ² , screw connection	KXB35E
Earth terminal, 70mm ² , screw connection	KXB70E



KXA02LH

Phase

Description	Cat ref.
Feed-through terminal -phase , 2,5mm ² , 800V-24A, screw connection	KXA02LH
Feed-through terminal-phase , 4mm ² , 800V/32A, screw connection	KXA04LH
Feed-through terminal-phase , 6mm ² , 1000V/41A, screw connection	KXA06LH
Feed-through terminal -phase , 10mm ² , 400V/57A, screw connection	KXA10L
Feed-through terminal-phase, 16mm ² , 400V/76A, screw connection	KXA16L
Feed-through terminal-phase, 35mm ² , 400V/125A, screw connection	KXA35L