

Auxiliary contact 2C LBS 20-160A

HZC312

Side mounting
2
-20 70 °C