



MBN116A

B Curve

Description	Cat ref.
MCB 1P 6kA B-16A 1M	MBN116A
MCB 1P 6kA B-50A 1M	MBN150A
MCB 1P 6kA B-63A 1M	MBN163A
MCB 1P 6kA B-6A 1M	MBN106W
MCB 1P 6kA B-16A 1M	MBN116W
MCB 1P 6kA B-20A 1M	MBN120W
MCB 1P 6kA B-25A 1M	MBN125W
MCB 1P 6kA B-32A 1M	MBN132W
MCB 1P 6kA B-40A 1M	MBN140W
MCB 1P 6kA B-50A 1M	MBN150W
MCB 1P 6kA B-63A 1M	MBN163W
MCB 1P 6kA B-10A 1M	MBN110W



MCN106A

C Curve

Description	Cat ref.
MCB 1P 6kA C-6A 1M	MCN106A
MCB 1P 6kA C-10A 1M	MCN110A
MCB 1P 6kA C-16A 1M	MCN116A
MCB 1P 6kA C-20A 1M	MCN120A
MCB 1P 6kA C-40A 1M	MCN140A



MU106A

C Curve without Accessories

Description	Cat ref.
MCB 1P 6kA C-6A 1M	MU106A
MCB 1P 6kA C-10A 1M	MU110A
MCB 1P 6kA C-16A 1M	MU116A
MCB 1P 6kA C-20A 1M	MU120A
MCB 1P 6kA C-25A 1M	MU125A
MCB 1P 6kA C-32A 1M	MU132A
MCB 1P 6kA C-40A 1M	MU140A
MCB 1P 6kA C-50A 1M	MU150A
MCB 1P 6kA C-63A 1M	MU163A